



# IMPORTANT!

M&P®15-22 CONSUMER SAFETY ALERT  
AND INSPECTION PROCEDURE

**SMITH & WESSON IS RECALLING EVERY M&P15-22 RIFLE  
MANUFACTURED BEFORE FEBRUARY 1, 2019.**

**STOP USING YOUR M&P15-22 UNTIL IT HAS BEEN INSPECTED AND  
YOUR BOLT REPLACED (IF NECESSARY).**

Smith & Wesson has identified two M&P15-22 firearms from recent production on which the breech face counter bore depth was not within manufacturing specification. In those firearms, the lack of depth may allow the bolt, upon closing, to crush the rim of the case, causing the round to fire, cycling the bolt, and potentially resulting in multiple discharges without depressing the trigger.

Come in to OnTarget and  
**GET YOUR RIFLE TESTED FOR FREE!**

*NOTE: You do not have to bring the entire rifle. You only need to bring the bolt.*



ONTARGETSITE.COM

560 Beechcraft Lane  
Crystal Lake, IL 60012 | 815.477.2020

@OnTargetTTC   